

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/22/2017

Submitted Date:

03/23/2017

Document Number:

666803047

FIELD INSPECTION FORM

Loc ID 335358 Inspector Name: Murray, Richard On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100185
 Name of Operator: ENCANA OIL & GAS (USA) INC
 Address: 370 17TH ST STE 1700
 City: DENVER State: CO Zip: 80202-

Findings:

8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Contact, General		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261630	WELL	PR	06/04/2002	GW	045-07970	COUEY 30-10A1 (O30NE)	PR
272414	WELL	PR	12/02/2004	GW	045-10075	COUEY 30-9 (O30NE)	PR
273477	WELL	PR	11/04/2004	GW	045-10252	COUEY 30-16 (O30NE)	PR
282075	WELL	PR	06/12/2006	GW	045-11619	COUEY 30-9C (O30NE)	PR
282076	WELL	PR	06/12/2006	GW	045-11618	COUEY 30-15B (O30NE)	PR

General Comment:

Comment:							
Corrective Action:				Date:			
Contents	#	Capacity	Type	Tank ID	SE GPS		
METHANOL	1	1000 GAL	STEEL AST		,		
Comment:		Centralized battery					
Corrective Action:				Date:			
Paint							
Condition							
Other (Content)							
Other (Capacity)							
Other (Type)							
Berms							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Comment:							
Corrective Action:				Date:			
Contents	#	Capacity	Type	Tank ID	SE GPS		
CONDENSATE	2	500 BBLs	STEEL AST		39.492111,107.707102		
Comment:							
Corrective Action:				Date:			
Paint							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
Berms							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:							
Corrective Action:				Date:			
Venting:							
Yes/No	NO						
Comment:							
Corrective Action:				Date:			
Flaring:							
Type							
Comment:							
Corrective Action:				Date:			

Inspected Facilities									
Facility ID:	<u>261630</u>	Type:	<u>WELL</u>	API Number:	<u>045-07970</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Plunger lift</u>								
Corrective Action:								Date:	
Facility ID:	<u>272414</u>	Type:	<u>WELL</u>	API Number:	<u>045-10075</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Plunger lift</u>								
Corrective Action:								Date:	
Facility ID:	<u>273477</u>	Type:	<u>WELL</u>	API Number:	<u>045-10252</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Plunger lift</u>								
Corrective Action:								Date:	
Facility ID:	<u>282075</u>	Type:	<u>WELL</u>	API Number:	<u>045-11619</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Plunger lift</u>								
Corrective Action:								Date:	
Facility ID:	<u>282076</u>	Type:	<u>WELL</u>	API Number:	<u>045-11618</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Plunger lift</u>								
Corrective Action:								Date:	

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Seeding	Pass					
Ditches	Pass					
		Ditches	Pass			
		Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT