

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/16/2017

Submitted Date:

03/23/2017

Document Number:

671000536**FIELD INSPECTION FORM**Loc ID 323850 Inspector Name: LUJAN, CARLOS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Kasten, Matt		Matthew.Kasten@encana.com	Environmental
Middleton, Brett		Brett.Middleton@encana.com	Environmental Specialist
Fischer, Alex		alex.fischer@state.co.us	Environmental Supervisor, NW
Lujan, Carlos		carlos.lujan@state.co.us	EPS, NW Region
Spencer, Stan		stan.spencer@state.co.us	EPS, NW Region

General Comment:

Environmental Site Inspection conducted on 03/16/2017. On Site with Brett Middleton from Encana. Sunny, warm and dry. Label at the entrance with emergency phone number. Large pad; fenced wellhead; 210 bbls produced water/condensate tank labeled. Secondary containment lined and with metal ring. No staining, junk or trash was observed on the premises. A soil vapor extraction system consisting of three wells connected to a pump powered by solar energy was running at the time of the inspection. Hydrocarbon odor was perceived coming out of the SVE system. See REM 7916.

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Environmental**Spills/Releases:**

Type of Spill: _____

Estimated Spill Volume: _____

Comment: Remediation system was installed in 2013. It consisted of a wind powered SVE system. Recently, Encana connected a pump to the extraction wells to improve bio-remediation and vapor extraction. No progress report has been submitted to the COGCC so far.

Corrective Action: Submit a progress report describing past and present activities as well as results obtained/measured so far. Indicate what activities are planned moving forward to complete remediation and close the project. Include a timetable of planned activities including soil boring and sampling.

Date: 04/28/2017

Reportable: _____

GPS: Lat _____ Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
671000537	Wellhead and Tank	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4107190
671000538	Pump, air filter and batteries	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4107191
671000539	SVE System	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4107192