



**Photo 1: View of the project area from the northeastern corner facing center.**



**Photo 2: View of the northern portion of the project area from the northeastern corner facing westward. Cobble diversion channel is filling with sediment and will soon need maintenance.**



**Photo 3: View of the eastern portion of the project area from the northeastern corner facing southward.**



**Photo 4: View of wattles that are no longer functioning in the eastern portion of the project area.**



**Photo 5: View of barbed wire debris in the southern portion of the project area.**



**Photo 6: View pipe and netting debris in the eastern portion of the project area that needs to be removed.**



**Photo 7: View of an erosional channel forming in the southern portion of the project area that needs stabilization.**