

Inspection Photos
Location Name: Ptasynski 5
API: 05-081-06493



Photo 1. View at entrance to location facing northeast.

Inspection Photos
Location Name: Ptasynski 5
API: 05-081-06493



Photo 2. View of pit standing at northeast corner looking southwest. Water in center is bubbling.



Photo 3. View of pit standing at southeast corner looking northwest during 6/15/2016 inspection.

Inspection Photos
Location Name: Ptasynski 5
API: 05-081-06493



Photo 4. Pit behind separator standing at northwest corner looking southeast.



Photo 5. Pit behind separator standing at northwest corner looking southeast from 6/15/2016 inspection.

Inspection Photos
Location Name: Ptasynski 5
API: 05-081-06439




Photo 6. Pit no longer bubbling. Photo courtesy of Clay Evans.




Photo 7. Replaced valve. Photo courtesy of Clay Evans.