

Inspection Photos
Location Name: Ptasynski 1X
API: 05-081-06614



Photo 1. View at entrance to location facing west.

Inspection Photos
Location Name: Ptasynski 1X
API: 05-081-06614



Photo 2. ~18 foot setback between pump jack and heated separator.



Photo 3. Missing tank label.

Inspection Photos
Location Name: Ptasynski 1X
API: 05-081-06614



Photo 4. Stained soil at loadout.



Photo 4. Partially labeled methanol container.

Inspection Photos
Location Name: Ptasynski 1X
API: 05-081-06614



Photo 6. View of pit facing southeast.



Photo 7. Landfarm area.