

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/22/2017

Submitted Date:

03/26/2017

Document Number:

673404303

FIELD INSPECTION FORM

Loc ID 312975 Inspector Name: Waldron, Emily On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10407
Name of Operator: ANTLER ENERGY LLC
Address: PO BOX 104
City: BAGGS State: WY Zip: 82321

Findings:

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Evans, Clay		antlerenergy@yahoo.com	
Neidel, Kris		kris.neidel@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223131	WELL	PR	06/30/2005	GW	081-06493	PTASYNSKI 5	PR

General Comment:

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	At entrance.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 307-380-7616

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PIT		
Comment:			
Corrective Action:		Date:	

Equipment:

Type			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	#		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		

Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		40.929260,-108.341930
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:	Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 223131 Type: WELL API Number: 081-06493 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No apparent soil migration; erosion or soil movement.

Corrective Action: _____ Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: _____ Lined: _____ Pit ID: _____ Lat: 40.929540 Long: -108.341990

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____

Corrective Action _____ Date: c

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment: _____

Corrective Action _____ Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: _____

Corrective Action _____ Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment: Pit bubbling with water coming up through snow. Hissing sound heard out of wellhead, did not hear plunger come up or down. Inspector called emergency contact number listed on location and spoke with Clay Evans of Antler Energy. Mr. Evans sent pumper out and replaced leaking valve to stop leak. Photos of replaced valve included courtesy of Mr. Evans. 2 pits on location. Only 1 pit ID in database, 100374. Coordinates above taken from SE corner of pit.

Corrective Action Please work with COGCC environmental staff Kris Neidel kris.neidel@state.co.us 970-871-1963 to identify if this pit ID is appropriate and to close pit if not in use or properly permit pit if in use and not associated with the above ID. Date: 07/18/2016

Type: _____ Lined: _____ Pit ID: _____ Lat: 40.929280 Long: -108.341530

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____

Corrective Action _____ Date: c

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment:		Date:
Corrective Action		
Netting:		
Netting Type:	Netting Condition:	
Comment:		Date:
Corrective Action		
Anchor Trench Present:	Oil Accumulation:	2+ feet Freeboard:
Comment:	Pit behind seperator. 2 pits on location. Only 1 pit ID in database, 100374. Coordinates above taken from NW corner of pit.	
Corrective Action	Please work with COGCC environmental staff Kris Neidel kris.neidel@state.co.us 970-871-1963 to identify if this pit ID is appropriate and to close pit if not in use or properly permit pit if in use and not associated with the above ID.	
		Date: <u>07/18/2016</u>

COGCC Comments		
Comment	User	Date
Pit bubbling with water coming up through snow. Hissing sound heard out of wellhead, did not hear plunger come up or down. Inspector called emergency contact number listed on location and spoke with Clay Evans of Antler Energy. Mr. Evans sent pumper out and replaced leaking valve to stop leak. Photos of replaced valve included courtesy of Mr. Evans.	waldrone	03/22/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673404333	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4108978