

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

03/17/2017

Submitted Date:

03/20/2017

Document Number:

679400034**FIELD INSPECTION FORM**

Loc ID	Inspector Name:	On-Site Inspection	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 3 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
	CHESSON, BOB	2A Doc Num:	

**Operator Information:**OGCC Operator Number: 10548Name of Operator: HRM RESOURCES II LLCAddress: 410 17TH STREET #1600City: DENVER State: CO Zip: 80202**Contact Information:**

Contact Name	Phone	Email	Comment
Montoya, John		john.montoya@state.co.us	
Pape, Terry	(970) 768-5700	tpape@hrmres.com	
Axelsson, John		john.axelsson@state.co.us	
Arauza, Steven		steven.arauza@state.co.us	
Precup, Jim		james.precup@state.co.us	
MacLaren, Joe		joe.maclaren@state.co.us	

**General Comment:**

COGCC environmental staff inspection. COGCC field inspector inspection and flowline integrity staff inspection (#674603227, #685502288). Spill release point leak from a 2-inch flowline in drainage. Fluids daylighted and flowed approximately 900 feet downstream to north. Some minor surface water ponding located from just north of the release location excavation to approximately 300 feet downstream. Remaining drainage is dry. Clean-up to date consisting of removal of impacted surface soils in drainage. Fluid in release location excavation is groundwater which is periodically removed and transported to HRM's injection facility for disposal. See photos (attached)

Please provide soils disposal documentation in supplemental spill/release submittal(s).

**Environmental****Spills/Releases:**

Type of Spill: OIL

Estimated Spill Volume: 5

Comment: Spill #401234377 reported from a flowline leak on 3/15/17. Approximately 3- to 5-bbls of fluid (produced water and crude oil) released from a corroded flowline into Horse Creek, an intermittent drainage. Horse Creek did not have any live water drainage at the time of the spill. Operator actively engaged in clean-up actions as soon as discovered and ongoing clean-up actions observed during inspection. COGCC notified CDPHE per MOA on 3/16/17.

Corrective Action: Submit either release closure documentation or form 27 for further clean-up actions by no later than 5/31/2017

Date: 05/31/2017

Reportable: YES

GPS: Lat

Long

Proximity to Surface Water:

Depth to Ground Water:

**Water Well Complaint:**

Lat

Long

DWR Receipt Num:

Owner Name:

GPS :

**Field Parameters:**

Sample Location:

Comment:

**COGCC Comments**

Comment

User

Date

COGCC environmental staff inspection. COGCC field inspection inspection and flowline integrity staff inspections (#674603227, #685502288). Spill release point leak from a 2-inch flowline in drainage. Fluids daylighted and flowed approximately 900 feet downstream to north. Some minor surface water ponding located from just north of the release location excavation to approximately 300 feet downstream. Remaining drainage is dry. Clean-up to date consisting of removal of impacted surface soils in drainage. Fluid in release location excavation is groundwater which is periodically removed and transported to HRM's injection facility for disposal. See photos (attached)

chessonr

03/20/2017

Please provide soils disposal documentation in supplemental spill/release submittal(s).

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401237312	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4102658">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4102658</a>
679400035	Flowline excavation site. GW in excavation w/adsorbent pads	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4102649">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4102649</a>
679400036	At excavation south end looking at dry drainage	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4102650">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4102650</a>
679400037	Looking north just north of release excavation	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4102651">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4102651</a>
679400038	Scraped drainage north	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4102652">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4102652</a>
679400039	Scraped drainage north w/workers	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4102653">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4102653</a>
679400040	Scraped drainage w/workers	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4102654">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4102654</a>
679400041	E-mail notification to CDPHE WQCD	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4102655">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4102655</a>