

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401243805

Date Received:

03/27/2017

FIR RESOLUTION FORM

Overall Status: BOTH

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

2 CA Completed
2 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290
Name of Operator: K P KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
<u>Axelson, John</u>		<u>john.axelson@state.co.us</u>
<u>Susana Lara-Mesa</u>	<u>303-825-4822</u>	<u>cogcc@kpk.com</u>
<u>MacLaren, Joe</u>		<u>joe.maclaren@state.co.us</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 681700424
Inspection Date: 03/22/2017 FIR Submit Date: 03/23/2017 FIR Status:

Inspected Operator Information:

Company Name: K P KAUFFMAN COMPANY INC Company Number: 46290
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 311297

Location Name: SELTZER-61N67W Number: 34NWSW County: WELD
Qtrqr: NWS Sec: 34 Twp: 1N Range: 67W Meridian: 6
W
Latitude: 40.006130 Longitude: -104.883770

FACILITY - API Number: 05-123-00 Facility ID: 240683

Facility Name: SELTZER Number: 1-A
Qtrqr: NWS Sec: 34 Twp: 1N Range: 67W Meridian: 6
W
Latitude: 40.006130 Longitude: -104.883770

CORRECTIVE ACTIIONS:

1 CA# 68655

Corrective Action: Repair berms per Rule 605.a.(4). Date: 04/23/2017
Response: CA COMPLETED Date of Completion: 03/27/2017

Berms were repaired. See pictures attached

Operator
Comment:

COGCC Decision:

COGCC
Representative:

2 CA# 68656

Corrective Action: Describe source of release and repairs made to equipment. If release was greater than 1 bbl, file Form 19 within 72 hours of discovery of the release. Contact the Engineering Integrity department to discuss flowline testing requirements per Rule 1101.e. Refer to the 1101 and 1102 guidance document for further details.

Date: 03/31/2017

Response: CA COMPLETED

Date of Completion: 03/23/2017

Operator
Comment:

The separator flooded during a manual unload. The release was under 1 bbl. There was no flowline release.

COGCC Decision:

COGCC
Representative:

3 CA# 68657

Corrective Action: Immediately install sign to comply with Rule 210.b.

Date: 09/07/2014

Response: FACTUAL REVIEW REQUEST

Basis for Review: Action requested was already completed prior to the inspection

Operator
Comment:

The tank battery only serves one well and it is referenced in the existing tank battery sign.

COGCC Decision:

COGCC
Representative:

4 CA# 68658

Corrective Action: Sample impacted soil at water meter and remit analytical results to verify whether or not the impact is related to KPK operations.

Date: 04/23/2017

Response: FACTUAL REVIEW REQUEST

Basis for Review: Corrective action dates are not attainable

Operator
Comment:

The flowline tested next to the surface owner's meter is a consolidation line carrying fluids from multiple wells and multiple formations. The flowline was tested and charted and there are no integrity issues found. The chart is attached to this form. It is unclear what soil testing is requested.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Susana Lara-Mesa Signed: _____

Title: VP Engineering Date: 3/27/2017 10:36:41 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
401243847	Tank Battery Photos
401243852	Well Photos
401243859	Consolidation Pressure Test

Total Attach: 3 Files