

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/09/2017

Submitted Date:

03/27/2017

Document Number:

678200654

FIELD INSPECTION FORM

Loc ID 312228 Inspector Name: YOUNG, ROB On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 95620
Name of Operator: WESTERN OPERATING COMPANY
Address: 518 17TH ST STE 200
City: DENVER State: CO Zip: 80202

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
Hart, Dale	719-688-1638	dale@westernoperating.com	
JAMES, STEVEN D	(303) 893-2438	steve@westernoperating.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256304	PIT	AC			-	PROPST 1-A	EI

General Comment:

Environmental inspection of produced water pit and associated erosion and adjacent rangeland impact.
Requesting a Form 27 describing remediation/reclamation of the affected areas.

Empty text area for additional comments or notes.

Inspected Facilities

Facility ID: 256304 Type: PIT API Number: - Status: AC Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: The pit berms are eroding and depositing sediment onto adjacent rangelands. Severe erosion is occurring on the northeast corner of the produced water pit.

Corrective Action: Submit an eForm 27 describing how the produced water pit berms will be improved, erosion controlled and the impacted surfaces will be reclaimed.

Date: 04/10/2017

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 256304 Lat: 40.892996 Long: -103.264618

Reference Point: _____ Other: _____ Length: 80 Width: 90

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____

Corrective Action _____

Date:

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment: _____

Corrective Action _____

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: _____

Corrective Action _____

Date: _____

Anchor Trench Present: _____ Oil Accumulation: NO 2+ feet Freeboard: YES

Comment: _____

Corrective Action _____

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
678200655	Location photographs	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4110282
678200656	Aerial photograph with erosion/impacted area outline	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4110283