

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/20/2017

Submitted Date:

03/21/2017

Document Number:

680101591

**FIELD INSPECTION FORM**

Loc ID 449385 Inspector Name: Colby, Lou On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: PO BOX 370  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

- 7 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

| Contact Name | Phone | Email                              | Comment                         |
|--------------|-------|------------------------------------|---------------------------------|
|              |       | COGCCInspectionReports@terraep.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name  | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 449386      | WELL | XX     | 02/28/2017  |            | 045-23434 | WARE SR 533-12 | CI          |
| 449387      | WELL | XX     | 02/28/2017  |            | 045-23435 | WARE SR 514-12 | CI          |
| 449388      | WELL | XX     | 02/28/2017  |            | 045-23436 | WARE SR 14-12  | CI          |
| 449389      | WELL | XX     | 02/28/2017  |            | 045-23437 | WARE SR 324-12 | CI          |
| 449390      | WELL | XX     | 02/28/2017  |            | 045-23438 | WARE SR 34-12  | CI          |
| 449391      | WELL | XX     | 02/28/2017  |            | 045-23439 | WARE SR 23-12  | CI          |
| 449392      | WELL | XX     | 02/28/2017  |            | 045-23440 | WARE SR 423-12 | CI          |
| 449393      | WELL | XX     | 02/28/2017  |            | 045-23441 | WARE SR 513-12 | CI          |
| 449394      | WELL | XX     | 02/28/2017  |            | 045-23442 | WARE SR 523-12 | CI          |
| 449395      | WELL | XX     | 02/28/2017  |            | 045-23443 | WARE SR 413-12 | CI          |
| 449396      | WELL | XX     | 02/28/2017  |            | 045-23444 | WARE SR 512-12 | CI          |
| 449397      | WELL | XX     | 02/28/2017  |            | 045-23445 | WARE SR 24-12  | CI          |
| 449398      | WELL | XX     | 02/28/2017  |            | 045-23446 | WARE SR 524-12 | CI          |
| 449399      | WELL | XX     | 02/28/2017  |            | 045-23447 | WARE SR 522-12 | CI          |
| 449400      | WELL | XX     | 02/28/2017  |            | 045-23448 | WARE SR 313-12 | CI          |
| 449401      | WELL | XX     | 02/28/2017  |            | 045-23449 | WARE SR 412-12 | CI          |
| 449402      | WELL | XX     | 02/28/2017  |            | 045-23450 | WARE SR 424-12 | CI          |
| 449403      | WELL | XX     | 02/28/2017  |            | 045-23451 | WARE SR 334-12 | CI          |
| 449404      | WELL | XX     | 02/28/2017  |            | 045-23452 | WARE SR 323-12 | CI          |
| 449405      | WELL | XX     | 02/28/2017  |            | 045-23453 | WARE SR 314-12 | CI          |
| 449406      | WELL | XX     | 02/28/2017  |            | 045-23454 | WARE SR 13-12  | CI          |
| 449407      | WELL | XX     | 02/28/2017  |            | 045-23455 | WARE SR 414-12 | CI          |
| 449408      | WELL | XX     | 02/28/2017  |            | 045-23456 | WARE SR 433-12 | CI          |
| 449409      | WELL | XX     | 02/28/2017  |            | 045-23457 | WARE SR 534-12 | CI          |

**General Comment:**

This is a Construction and Stormwater Inspection. Form 42 (Notice of Construction) has been Filed for this Location; Start Date as /13/2017. .Conditions at time of Inspection were Overcast, Hazy at 68 degrees.

**Location Construction**

Location ID: 449385 CDP: \_\_\_\_\_

**Comment:** Pipe line work had commenced on 3/13/17, line from Lower Youberg Loc to new Location Installed. Site has had Bush clipped/beat. Construction on Access road was in Progress with two Link Belts Operating at time of Inspection.

Corrective Action: \_\_\_\_\_ **Date:** \_\_\_\_\_

**Form 2A COAs:**

**Comment:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_ **Date:** \_\_\_\_\_

**Wildlife BMPs:**

**Comment:** This location is included in a Wildlife Mitigation Plan. The facility lies within the external buffer zone of the Beaver Creek 317B area. Therefore by COGCC rule, the 317B buffer zone classifies the facility as being in a sensitive area.

Corrective Action: \_\_\_\_\_ **Date:** \_\_\_\_\_

**Stormwater:**

| Erosion BMPs     | Present | Other BMPs | Present |
|------------------|---------|------------|---------|
| SLOPE ROUGHENING | No      |            |         |

**Comments:** Erosion BMPs: Construction was just commencing. Contractor indicated that Roughening or Appropriate BMP would be installed by Day end at juncture of Access Road entrance with Local Scribner Lane Rd.

Other BMPs: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ **Date:** \_\_\_\_\_

**Comment:** Contractor Indicated that exploratory Pipe line bore holes at juncture of Access Road entrance with Local Rd would be covered to prevent Endangerment of Wildlife by end of Day. Refer to Photos attached.

**Corrective Action:** \_\_\_\_\_ **Date:** \_\_\_\_\_

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

## Inspected Facilities

|                            |                   |                              |                   |                         |
|----------------------------|-------------------|------------------------------|-------------------|-------------------------|
| Facility ID: <u>449386</u> | Type: <u>WELL</u> | API Number: <u>045-23434</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>449387</u> | Type: <u>WELL</u> | API Number: <u>045-23435</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>449388</u> | Type: <u>WELL</u> | API Number: <u>045-23436</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>449389</u> | Type: <u>WELL</u> | API Number: <u>045-23437</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>449390</u> | Type: <u>WELL</u> | API Number: <u>045-23438</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>449391</u> | Type: <u>WELL</u> | API Number: <u>045-23439</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>449392</u> | Type: <u>WELL</u> | API Number: <u>045-23440</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>449393</u> | Type: <u>WELL</u> | API Number: <u>045-23441</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>449394</u> | Type: <u>WELL</u> | API Number: <u>045-23442</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>449395</u> | Type: <u>WELL</u> | API Number: <u>045-23443</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>449396</u> | Type: <u>WELL</u> | API Number: <u>045-23444</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>449397</u> | Type: <u>WELL</u> | API Number: <u>045-23445</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>449398</u> | Type: <u>WELL</u> | API Number: <u>045-23446</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>449399</u> | Type: <u>WELL</u> | API Number: <u>045-23447</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>449400</u> | Type: <u>WELL</u> | API Number: <u>045-23448</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>449401</u> | Type: <u>WELL</u> | API Number: <u>045-23449</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>449402</u> | Type: <u>WELL</u> | API Number: <u>045-23450</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>449403</u> | Type: <u>WELL</u> | API Number: <u>045-23451</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |
| Facility ID: <u>449404</u> | Type: <u>WELL</u> | API Number: <u>045-23452</u> | Status: <u>XX</u> | Insp. Status: <u>CI</u> |

|                     |            |                       |            |                  |
|---------------------|------------|-----------------------|------------|------------------|
| Facility ID: 449405 | Type: WELL | API Number: 045-23453 | Status: XX | Insp. Status: CI |
| Facility ID: 449406 | Type: WELL | API Number: 045-23454 | Status: XX | Insp. Status: CI |
| Facility ID: 449407 | Type: WELL | API Number: 045-23455 | Status: XX | Insp. Status: CI |
| Facility ID: 449408 | Type: WELL | API Number: 045-23456 | Status: XX | Insp. Status: CI |
| Facility ID: 449409 | Type: WELL | API Number: 045-23457 | Status: XX | Insp. Status: CI |

**COGCC Comments**

| Comment   | User   | Date       |
|---|--------|------------|
| <a href="#">Follow up inspection(s) will proceed while construction of location is IN-PROCESS. Refer to Photos attached for more detail</a> | colbyl | 03/21/2017 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 401241095    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4106220">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4106220</a> |
| 680101592    | Inspection Photos    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4106214">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4106214</a> |