

Inspection Photos
Location Name: State 36-3-9
API: 05-123-19794



Photo from prior inspection by A Trujillo



Photo 1: Berms low to nonexistent

Inspection Photos
Location Name: State 36-3-9
API: 05-123-19794



Photo from prior inspection by A Trujillo



Photo 2: Tanks have been labeled with capacity

Inspection Photos
Location Name: State 36-3-9
API: 05-123-19794



Photo from prior inspection by A Trujillo

Photo 3: Sign illegible, does not mention state battery

Inspection Photos
Location Name: State 36-3-9
API: 05-123-19794



Photo from prior inspection by A Trujillo



Photo 4: Weeds on location

Inspection Photos
Location Name: State 36-3-9
API: 05-123-19794



Photo from prior inspection by A Trujillo



Photo 5: Stormwater runoff on SE corner of location

Inspection Photos
Location Name: State 36-3-9
API: 05-123-19794



Photo from prior inspection by A Trujillo



Photo 6: Site photo for reclamation

Inspection Photos
Location Name: State 36-3-9
API: 05-123-19794



Photo from prior inspection by A Trujillo



Photo 7: Unused rods

Inspection Photos
Location Name: State 36-3-9
API: 05-123-19794



Photo from prior inspection by A Trujillo



Photo 8: Stormwater erosion on N side of location, looking N

Inspection Photos
Location Name: State 36-3-9
API: 05-123-19794



Photo from prior inspection by A Trujillo

Photo 9: Unpermitted pit

Inspection Photos
Location Name: State 36-3-9
API: 05-123-19794



Photo from prior inspection by A Trujillo



Photo 10: Wellhead sign

Inspection Photos
Location Name: State 36-3-9
API: 05-123-19794



Photo from prior inspection by C Pesicka



Photo 11: Stained soil has been addressed

Inspection Photos
Location Name: State 36-3-9
API: 05-123-19794



Photo from prior inspection by C Pesicka



Photo 12: Stained soil has been addressed

Inspection Photos
Location Name: State 36-3-9
API: 05-123-19794



Photo from prior inspection by C Pesicka



Photo 13: Pit wall built up, 2+ feet of freeboard

Inspection Photos
Location Name: State 36-3-9
API: 05-123-19794



Photo 14: ECD disconnected from treating equipment



Photo 15: Low fence, manure inside tank battery

Inspection Photos
Location Name: State 36-3-9
API: 05-123-19794



Photo 16: Fence post exposed on NW corner of pit