

# Construction and Stormwater Inspection

March 27, 2017

Operator: KERR MCGEE OIL & GAS ONSHORE LP  
#47120

Location ID: 331768

Weld County, CO

SESE Section 22 T3N R68W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: HILGERS /8N3-34HZ  
Location ID: 331768



**Photo 1.** Photo taken from the entrance of location, facing North. Vehicle tracking pad installed and appears to be properly functioning.



**Photo 2.** Photo taken from the southeast location, facing North. Ditch and berm BMP installed around perimeter of location.

Inspection Photos  
Location Name: HILGERS /8N3-34HZ  
Location ID: 331768



**Photo 3.** Photo taken from the northeast location, facing North. Sediment trap installed with outlet protection in the form of a blanket and wattle.



**Photo 4.** Photo taken from the northeast location, facing West. Culvert installed in conjunction with the ditch and berm BMP that is directed to the sediment trap.

Inspection Photos  
Location Name: HILGERS /8N3-34HZ  
Location ID: 331768



**Photo 5.** Photo taken from the northern production location, facing West. Topsoil salvaged and stored along the northern and western perimeter of the production location.



**Photo 6.** Photo taken from the northern location, facing West. Ditch and berm BMP installed around perimeter of location.

Inspection Photos  
Location Name: HILGERS /8N3-34HZ  
Location ID: 331768



**Photo 7.** Photo taken from the northwest location, facing South. Sediment trap installed with outlet protection in the form of a blanket and wattle.



**Photo 8.** Photo taken from the northwest location, facing Southeast. Culvert has been installed directing stormwater runoff from the production area to the northwest sediment trap.

Inspection Photos  
Location Name: HILGERS /8N3-34HZ  
Location ID: 331768



**Photo 9.** Photo taken from the western location, facing South. Ditch and berm BMP installed around perimeter of location.



**Photo 10.** Photo taken from the western production location, facing North. Topsoil salvaged and stored along the northern and western perimeter of the production location.

Inspection Photos  
Location Name: HILGERS /8N3-34HZ  
Location ID: 331768



**Photo 11.** Photo taken from the southern location, facing East. Ditch and berm BMP installed around perimeter of location.