

Construction and Stormwater Inspection

March 27, 2017

Operator: KERR MCGEE OIL & GAS ONSHORE LP
#47120

Location ID: 446137

Weld County, CO

NESE Section 22 T3N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: HILGERS /12N-22HZ
Location ID: 446137



Photo 1. Photo taken from the entrance of location, facing North. Vehicle tracking pad installed and appears to be properly functioning.



Photo 2. Photo taken from the southeast location, facing West. Ditch and berm BMP installed around north, west, and south perimeter of location. Topsoil stored along the southern perimeter of location.

Inspection Photos
Location Name: HILGERS /12N-22HZ
Location ID: 446137



Photo 3. Photo taken from the southeast location, facing North. Cut slope appears to be temporarily stabilized but may need additional BMPs.



Photo 4. Photo taken from the northern location, facing West. Ditch and berm BMP installed around north, west, and south perimeter of location.

Inspection Photos
Location Name: HILGERS /12N-22HZ
Location ID: 446137



Photo 5. Photo taken from the northwest location, facing South. Ditch and berm BMP installed around north, west, and south perimeter of location.



Photo 6. Photo taken from the western location, facing South. Sediment trap installed with outlet protection in the form of a blanket and wattle.

Inspection Photos
Location Name: HILGERS /12N-22HZ
Location ID: 446137



Photo 7. Photo taken from the southwest location, facing South. Sediment trap installed with outlet protection in the form of a blanket and wattle.



Photo 8. Photo taken from the southern location, facing East. Ditch and berm BMP installed around north, west, and south perimeter of location.