

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/31/2017

Submitted Date:

03/31/2017

Document Number:

679700406

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
407304 _____ ALLISON, RICK _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 50560
Name of Operator: LECLAIR-WESTWOOD INC
Address: 518 17TH ST STE 1000
City: DENVER State: CO Zip: 80202

Findings:

- 3 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Burn, Diana		diana.burn@state.co.us	
Axelson, John		john.axelson@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242670	WELL	PA	11/19/1981	DA	123-10461	SEVERIN & CO. 1	EI
449709	SPILL OR RELEASE	AC			-	Severin & CO #1 wellhead #1	EI

General Comment:

COGCC Site Inspection of historical impacts discovered by Bayswater Exploration and Production during their re-entry and plugging of the Severin & Co. #1 well.

Inspected Facilities

Facility ID: 242670 Type: WELL API Number: 123-10461 Status: PA Insp. Status: EI

Facility ID: 449709 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Waste Management:

Type	Management	Condition	GPS (Lat) (Long)	
Oily Soil	Piles	Adequate		
Comment		Operator has stockpiled ~15 yds oily soil on liner, to be disposed at commercial facility		
Corrective Action				Date: _____

Spill/Remediation:

Comment: COGCC onsite to inspect and sample historical impacts discovered during re-entry and P&A of well. Operator had excavated approximately 15'x15'x5' to accomodate cut and cap of the well casing. Impacts are present in the sidewalls and floor of excavation. Excavated soil and sidewalls have hydrocarbon odor. Soil sample collected and delivered to laboratory for analysis for TPH-DRO, TPH-GRO and BTEX. Sample collected from northwest corner of excvation at approximately 4' below ground surface, Lat/Lon = 40.54330 / -104.79086

Corrective Action: _____ Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679700407	Soil Sample Chain of Custody	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4113942
679700408	View of stockpiled soil 1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4113943
679700409	View of stockpiled soil 2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4113944
679700410	From south side of excavatino looking north	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4113945
679700411	From east side of excavation looking west	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4113946