

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/29/2017

Submitted Date:

03/31/2017

Document Number:

669600031**FIELD INSPECTION FORM**Loc ID 325411 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	<a href="#">SW Inspection Reports</a>
Inspections, All		SanJuanCOGCC@bp.com	<a href="#">SW Inspection Reports</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214733	WELL	PR	11/11/1990	GW	067-06337	XAVIER 1	PR

**General Comment:**[See link at end of report for path to downloadable pictures.](#)

**Location**Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Corrective action complete. Tank labels have been placed on top of tank and are not visible from outside the containment ring. This issue has been identified on other locations and in process of being corrected. Labels need to be placed in conspicuous place to comply with Rule 210.		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		
Corrective Action:		Date: _____

**Good Housekeeping:**

Type	WEEDS		
Comment:	Corrective action completed.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Corrective action completed.			
Corrective Action:				Date:

**Venting:**

Yes/No		
Comment:		

Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 214733    Type: WELL    API Number: 067-06337    Status: PR    Insp. Status: PR

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
669600087	Labeled chemical tank.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114186">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114186</a>
669600088	Perimeter of location with weeds removed 1.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114187">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114187</a>
669600089	Labels on top of tank.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114189">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114189</a>
669600098	Location overview.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114190">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114190</a>
669600099	Perimeter of location with weeds removed 2.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114191">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114191</a>