

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/30/2017

Submitted Date:

03/31/2017

Document Number:

669600034

FIELD INSPECTION FORM

Loc ID 306917 Inspector Name: St John, William (Cal) On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

Findings:

5 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	SW Inspection Reports
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277748	WELL	PR	04/15/2010	GW	067-09045	FEDERAL 14-01 2	PR

General Comment:

[See link at end of report for path to downloadable pictures.](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type WEEDS

Comment: Corrective action completed. Additional monitoring maybe required as spring growth is emerging and may need treatment to avoid growth around production equipment.

Corrective Action:

Date:

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV STEEL		,
Comment: <input type="text"/>					
Corrective Action: <input type="text"/>					Date: <input type="text"/>

Paint

Condition Adequate

Other (Content)

Other (Capacity) 95 BBLs

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Corrective action completed. Additional monitoring maybe required as spring growth is emerging and may need treatment to avoid growth on containment berms.				
Corrective Action: <input type="text"/>				Date: <input type="text"/>

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type <input type="text"/>	<input type="text"/>
Comment: <input type="text"/>	<input type="text"/>
Corrective Action: <input type="text"/>	Date: <input type="text"/>

Inspected FacilitiesFacility ID: 277748 Type: WELL API Number: 067-09045 Status: PR Insp. Status: PR**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
669600113	Location overview.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114251
669600119	Weeds and grass removed from inside production equipment fencing.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114252
669600121	Weeds and grass removed from inside pump jack fencing.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114253
669600123	Emerging weeds and grass around and on berms.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114254