

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401249661  
Date Received:  
04/03/2017

## FIR RESOLUTION FORM

### CA Summary:

4 of 4 CAs from the FIR responded to on this Form

0 CA Completed  
4 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 10071  
Name of Operator: BARRETT CORPORATION\* BILL  
Address: 1099 18TH ST STE 2300  
City: DENVER State: CO Zip: 80202  
Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) Fax: ( )  
Email: \_\_\_\_\_

### Additional Operator Contact:

Contact Name	Phone	Email
Binschus, Chris		<a href="mailto:COGCC_FIR@billbarrettcorp.com">COGCC_FIR@billbarrettcorp.com</a> <a href="mailto:chris.binschus@state.co.us">chris.binschus@state.co.us</a>

### COGCC INSPECTION SUMMARY:

FIR Document Number: 682501788  
Inspection Date: 03/24/2017 FIR Submit Date: 03/28/2017 FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: BARRETT CORPORATION\* BILL Company Number: 10071  
Address: 1099 18TH ST STE 2300  
City: DENVER State: CO Zip: 80202

### LOCATION - Location ID: 449383

Location Name: Hawkins Number: 5-61-20\_19 SW21 County: \_\_\_\_\_  
Qtrqtr: NWS Sec: 21 Twp: 5N Range: 61W Meridian: 6  
Latitude: 40.385989 Longitude: -104.222578

### FACILITY - API Number: 05-123- -00 Facility ID: 449383

Facility Name: Hawkins Number: 5-61-20\_19 SW21  
Qtrqtr: NWS Sec: 21 Twp: 5N Range: 61W Meridian: 6  
Latitude: 40.385989 Longitude: -104.222578

### CORRECTIVE ACTIONS:

1 CA# 69347

Corrective Action: Install or repair BMP(s) in accordance with good engineering practices per Rule 1002.f.

Date: 04/04/2017

Response: FACTUAL REVIEW REQUEST

Basis for Review: Corrective action dates are not attainable

Operator Comment: BBC is asking for an extension to 4/11/17 as work was going to be completed 4/3 but after multiple rain/snow events since the inspection, the field area is muddy and doing work now would likely cause additional disturbances.

COGCC Decision: **Not Approved**

COGCC Representative:

COGCC Supervisor: FIRR is not approved due to the fact that adequate and sufficient stormwater control BMPs on location should have been properly implemented and constructed prior to a COGCC inspection. Stormwater controls should be in place to protect the site during inclement weather conditions. It appears that the BMPs lack good engineering practices such as outlet protection, etc.

2  CA# 69348

Corrective Action: Install or repair BMP(s) in accordance with good engineering practices per Rule 1002.f.

Date: 04/04/2017

Response: FACTUAL REVIEW REQUEST

Basis for Review: Corrective action dates are not attainable

Operator Comment: BBC is asking for an extension to 4/11/17 as work was going to be completed 4/3 but after multiple rain/snow events since the inspection, the field area is muddy and doing work now would likely cause additional disturbances.

COGCC Decision: **Not Approved**

COGCC Representative:

COGCC Supervisor: FIRR is not approved due to the fact that adequate and sufficient stormwater control BMPs on location should have been properly implemented and constructed prior to a COGCC inspection. Stormwater controls should be in place to protect the site during inclement weather conditions. It appears that the BMPs lack good engineering practices such as outlet protection, etc.

3  CA# 69349

Corrective Action: Install or repair BMP(s) in accordance with good engineering practices per Rule 1002.f.

Date: 04/04/2017

Response: FACTUAL REVIEW REQUEST

Basis for Review: Corrective action dates are not attainable

Operator Comment: BBC is asking for an extension to 4/11/17 as work was going to be completed 4/3 but after multiple rain/snow events since the inspection, the field area is muddy and doing work now would likely cause additional disturbances.

COGCC Decision: **Not Approved**

COGCC Representative:

COGCC Supervisor: FIRR is not approved due to the fact that adequate and sufficient stormwater control BMPs on location should have been properly implemented and constructed prior to a COGCC inspection. Stormwater controls should be in place to protect the site during inclement weather conditions. It appears that the BMPs lack good engineering practices such as outlet protection, etc.

4  CA# 69350

Corrective Action: Install or repair BMP(s) in accordance with good engineering practices per Rule 1002.f.

Date: 04/04/2017

Response: FACTUAL REVIEW REQUEST

Basis for Review: Corrective action dates are not attainable

Operator Comment: BBC is asking for an extension to 4/11/17 as work was going to be completed 4/3 but after multiple rain/snow events since the inspection, the field area is muddy and doing work now would likely cause additional disturbances.

COGCC Decision: **Not Approved**

COGCC  
Representative:

COGCC  
Supervisor:

FIRR is not approved due to the fact that adequate and sufficient stormwater control BMPs on location should have been properly implemented and constructed prior to a COGCC inspection. Stormwater controls should be in place to protect the site during inclement weather conditions. It appears that the BMPs lack good engineering practices such as outlet protection, etc.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tracey Fallang

Signed: \_\_\_\_\_

Title: Regulatory Manager

Date: 4/3/2017 1:09:41 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

401249661	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files