



photo 1: Facing northwest, there are signs of erosion occurring along the side of the access road.



photo 2: Facing southeast, erosion occurring in photo 1 is depositing sediment in this area and stormwater is flowing across the road causing erosion.



photo 3: Well sign is adequate.



photo 4: The sediment trap at the northwest side of the location is full of sediment.



photo 5: Facing southeast at the location. There are areas where vegetation has not established and soils are not stabilized.



photo 6: Sediment trap at the east side of the location is full of sediment.