



Photo 1: View of the project area from the southwestern corner facing center.



Photo 2: View of the western portion of the project area from the southwestern corner facing northward. Surrounding field and interim reclamation areas are not vegetated at this time.



Photo 3: View of the southern portion of the project area from the southwestern corner facing eastward.



Photo 4: View of area where stormwater erosion is occurring along the southern edge of the access road.



Photo 5: Another view of where erosion is occurring along the access road where wattles are no longer functioning.