



**Photo 1:** View of the project area from the southwestern corner facing center. Unused pipe should be removed.



**Photo 2:** View of the western portion of the project area from the southwestern corner facing northward. Revegetation is largely comprised shrubs such rubber rabbitbrush (*Chrysothamnus nauseosus*) and big sagebrush (*Artemisia tridentata*).



**Photo 3: View of the southern portion of the project area from the southwestern corner facing eastward.**



**Photo 4: View of area where it appears erosion is occurring within the western portion of the project area.**





**Photo 5: View of trash on the fence and within the northern revegetation area.**