

# Inspection Photos

03/31/2017

Operator: Whiting Oil and Gas #96155

Location ID: 444471

Inspection Doc. Number: 682501845

Weld County, CO

SWSE Section 25 T10N R58W

Aaron Trujillo

Reclamation Specialist

COGCC



Inspection Photos  
Operator: Whiting  
Location ID: 444471



**Photo 1:** Photo taken from the north end of the location, facing west. Photo shows additional inlet protection has been installed on sediment trap.



**Photo 2:** Photo taken from the north end of the location. Photo shows additional outlet drain constructed into sediment trap.

Inspection Photos  
Operator: Whiting  
Location ID: 444471



**Photo 3:** Photo taken from the outlet of the sediment trap on the north end of the location. Photo shows that outlet armoring from the drain was insufficient as stormwater erosion leading into the ditch is evident.



**Photo 4:** Photo taken from the access road on the north end of the location. Photo shows culvert has been smashed and in need of maintenance.



**Photo 5:** Photo taken from the northwest end of the location. Photo shows that additional inlet and outlet protection has been installed on the sediment traps.



**Photo 6:** Photo taken from the southwest corner of the location, facing east. Photo shows a stormwater and sediment trap has been constructed on this corner of the location. Trap appears to be in proper functioning condition.

Inspection Photos  
Operator: Whiting  
Location ID: 444471



**Photo 7:** Photo taken from the outlet of the sediment trap on the south end of the location. Photo shows that outlet armoring appears insufficient as stormwater erosion leading into the ditch is evident.



**Photo 8:** Photo taken from the outlet of the sediment trap on the south end of the location. Photo shows that outlet armoring appears insufficient as stormwater erosion leading into the ditch is evident.

Inspection Photos  
Operator: Whiting  
Location ID: 444471



**Photo 9:** Photo taken from the east end of the location. Photo shows additional inlet and outlet protection has been installed on sediment trap.



**Photo 10:** Photo taken from the northeast corner of the location, facing west. Photo shows example of an area of ditch with long stretches of downward slope without controls to mitigate stormwater velocity.