

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/24/2017

Submitted Date:

04/03/2017

Document Number:

685200255**FIELD INSPECTION FORM**Loc ID 320858 Inspector Name: LABOWSKIE, STEVE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**15 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, All		SanJuanCOGCC@bp.com	<a href="#">All Inspections</a>
Beebe, Sabre		sabre.beebe@bp.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449467	WELL	DG	03/21/2017		007-06325	Carmelita Gallegos A 3	DG

**General Comment:**[Inspection for new well on newly constructed pad only \(007-06325\). Producing well \(007-06124\) on previously constructed pad above.](#)

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	DRILLING/RECOMP		
Comment:	temporary drilling sign posted at entrance to access		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Note: no rig sign present at county road and access road at time of inspection (603.e(10))		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Appropriate emergency contact numbers and location information posted in doghouse		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: satisfactory (on temporary drilling sign)

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Location Construction**

Location ID: 449467

CDP: \_\_\_\_\_

Comment: see previous reclamation inspection doc#680601373

Corrective Action:

Date: \_\_\_\_\_

**Form 2A COAs:**

**Comment:** Spud is considered start of surface hole. Spud notice submitted electronically doc#401236768 submitted on 3/20/2017 for spud on 3/21/2017 (at least 48 hours required). According to field representative surface hole was started (well was spud) on 3/18/2017 by Mo-Te spudder rig. AWS 507 rigged up and conducted BOP test with 24# J-55 surface casing set at 363' on 3/21/2017.

Corrective Action: Comply with COA (notice of rig mobilization at least 48 hours) and Rule 316.c (at least 48 hours).

Date: 04/03/2017

**Wildlife BMPs:****Comment:** Corrective Action: **Date:** **Stormwater:**

Erosion BMPs	Present	Other BMPs	Present
--------------	---------	------------	---------

WADDLES		Covering Materials	Yes`
---------	--	--------------------	------

Comments: Erosion BMPs: Other BMPs: Corrective Action:  Date: 

SLOPE ROUGHENING	Yes		`
------------------	-----	--	---

Comments: Erosion BMPs: Other BMPs: Corrective Action:  Date: 

BERMS	Yes	Material Handling And Spill Prevention	Yes`
-------	-----	--	------

Comments: Erosion BMPs: Other BMPs: Corrective Action:  Date: 

DITCHES	Yes	Self Inspection	`
---------	-----	-----------------	---

Comments: Erosion BMPs: Other BMPs: Corrective Action:  Date: **Comment:** **Corrective Action:** **Date:** **On Site Inspection (305):**Surface Owner Contact Information:Name: Address: Phone Number: Cell Phone: Operator Rep. Contact Information:Landman Name: Phone Number: Date Onsite Request Received: Date of Rule 306 Consultation: Request LGD Attendance: LGD Contact Information:Name: Phone Number: Agreed to Attend: Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:	

**Inspected Facilities**Facility ID: 449467 Type: WELL API Number: 007-06325 Status: DG Insp. Status: DG**Well Drilling**

**Rig:** Rig Name: AWS 507 Pusher/Rig Manager: Justin, Bull  
Permit Posted: Yes Access Sign: No

**Well Control Equipment:**

Pipe Ram: YES Blind Ram: YES Hydri Type: YES  
Pressure Test BOP: Pass Test Pressure PSI: 1500 Safety Plan: YES

**Drill Fluids****Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: YES Semi-Closed Loop: \_\_\_\_\_  
Multi-Well: \_\_\_\_\_ Disposal Location: commercial off-site

**Comment:** 8 valid fire extinguishers, TIW valve w/ 2 darts on floor, flare set-up, designated smoking and muster areas, portable toilets.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction		Compaction				
Gravel		Gravel				

Comment: [see "location construction" page for comments on construction sormwater, COAs and BMPs](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685200267	loose perimeter berm and topsoil pile SE edge	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4116051">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4116051</a>
685200268	full/overflowing waddles SE side of location	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4116052">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4116052</a>