

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/22/2017

Submitted Date:

03/27/2017

Document Number:

674603258**FIELD INSPECTION FORM**
 Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
 _____ Maclaren, Joe _____ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 4680Name of Operator: DCP MIDSTREAM LPAddress: 370 17TH STREET - SUITE 2500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
JONES, JEANETTE		jajones@dcpmidstream.com	
Hazard, Ellice		ellice.hazard@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Hayes, Branden	970-373-8905	bshayes@dcpmidstream.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449651	SPILL OR RELEASE	AC	03/16/2017		-	Parker 16-15	EG

General Comment:

COGCC Integrity Inspection performed on March 22nd, 2017 in response to initial form 19 spill report Doc #401235312 received on 03/16/2017 that outlines: DCP Environmental was informed by DCP Pipeline group of a pipeline valve release near a DCP Operated meter run on March 3rd, 2017 around 9:00 am. At the time of discovery a small amount of liquid was present at the soil surface. The DCP Environmental group reviewed the pipeline release along with DCP Pipeline to investigate the release. During the investigation the size of the release was estimated at less than 1 barrel of condensate. DCP Pipeline group repaired the valve on March 3rd, 2017. The details of the observations made during this field inspection are available in the comment section of this report. Photo's have been uploaded and can be accessed via link(s) at the end of this report.

Inspected Facilities

Facility ID: 449651 Type: SPILL OR API Number: - Status: AC Insp. Status: EG

COGCC Comments

Comment	User	Date
DCP Midstream personnel were not on location at the time of this field inspection. The area of release has been cleaned up and re-contoured. As indicated on initial form 19 spill report doc #401235312; DCP Pipeline group repaired the valve on March 3rd, 2017. There were no pipeline or valve integrity issues/ no leaks observed at the time of this field inspection.	maclarej	03/27/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401245265	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4110351
674603267	Area of release adjacent/ north of meter run	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4110275
674603268	Valves and piping at meter run	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4110277
674603269	Pipe skid/ new valve near meter run	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4110278