

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/09/2017

Submitted Date:

03/27/2017

Document Number:

678200660**FIELD INSPECTION FORM**Loc ID 312292 Inspector Name: YOUNG, ROB On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 95620Name of Operator: WESTERN OPERATING COMPANYAddress: 518 17TH ST STE 200City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Hart, Dale	719-688-1638	dale@westernoperating.com	
James, Steven	(303) 893-2438	steve@westernoperating.com	<a href="#">All Inspections</a>
Axelson, John		john.axelson@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256303	PIT	AC			-	PROPST B-2	EI

**General Comment:**

Environmental inspection documenting erosion and vegetation kill related to produced water pit berm erosion. Oil skim culvert (tinhorn) requires closure under an approved Form 27.



## Reclamation - Storm Water - Pit

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Skimming/SettlingLined: NOPit ID: Lat: Long: Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Oil skim culvert.

Corrective Action

Submit a Form 27 describing the oil skim culvert (tinhorn) removal and confirmation soil sampling plan.Date: 04/14/2017c**Fencing:**Fencing Type: Fencing Condition: Comment: 

Corrective Action

Date: **Netting:**Netting Type: Netting Condition: Comment: 

Corrective Action

Date: Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard: Comment: 

Corrective Action

Date: Type: Produced WaterLined: NOPit ID: 256303Lat: 40.896586Long: -103.269408Reference Point: Other: Length: 160Width: 90**Lining:**Liner Type: Liner Condition: Comment: Substantial erosion from the south and west produced water pit berms has occurred. Vegetation needs to be restored.

Corrective Action

Submit a Form 27 for the remediation/reclamation of the affected areas.Date: 04/14/2017c**Fencing:**Fencing Type: Fencing Condition: Comment: 

Corrective Action

Date: **Netting:**Netting Type: Netting Condition:

Comment:		Date:
Corrective Action		
Anchor Trench Present:	Oil Accumulation:	2+ feet Freeboard:
Comment:		Date:
Corrective Action		

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401245293	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4110369">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4110369</a>
678200661	Location photographs	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4110286">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4110286</a>
678200662	Google Earth aerial showing salt kill outline	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4110287">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4110287</a>