

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/27/2017

Submitted Date:

03/28/2017

Document Number:

679700388

**FIELD INSPECTION FORM**

Loc ID 414174 Inspector Name: ALLISON, RICK On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10629  
Name of Operator: FIFTH CREEK ENERGY OPERATING COMPANY LLC  
Address: 5251 DTC PKWY STE 420  
City: GREENWOOD State: CO Zip: 80111

**Findings:**

- 6 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	<a href="#">COGCC Area Inspector</a>
Bill Irwin		birwin@fifthcreekenergy.com	<a href="#">VP Operations</a>
Sydney Smith		ssmith@fifthcreekenergy.com	<a href="#">Regulatory Analyst</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
413063	WELL	PR	03/24/2010	OW	123-30584	ELMER 8-31H	EI
448725	SPILL OR RELEASE	AC	03/22/2017		-	SPILL/RELEASE POINT	EI

**General Comment:**

[COGCC Environmental Inspection followup to spill 448725. Corrective actions regarding unused equipment \(frac tank stored\) and stained soil around separator and wellhead noted on Inspection #6684901439 have been completed.](#)

**Inspected Facilities**

Facility ID: 413063 Type: WELL API Number: 123-30584 Status: PR Insp. Status: EI

Facility ID: 448725 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

## Environmental

**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil	Piles	Adequate		
Comment		Soil stockpiled on liner on NW corner of pad, pending disposal		
Corrective Action				Date: _____

**Spill/Remediation:**

Comment: Spill remediation is in process. Targeted excavation around heater treater has occurred. Oily soil remains in excavation pending further removal or remediation.

Corrective Action:  Date: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment:

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401245708	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4110771">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4110771</a>
679700391	Excavation around vertical southside	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4110761">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4110761</a>
679700392	Excavation around vertical northside	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4110762">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4110762</a>
679700393	Excavation around piping inside treater bldg	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4110763">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4110763</a>
679700394	Oily soil stockpile in northwest corner of pad	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4110764">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4110764</a>