

Location			
Lease Road:			
Type	Access		
comment:	Trail through pasture		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign mounted to fence at wellhead		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Rods and tubing stored on location		
Corrective Action:	Remove unused equipment from location		Date: <u>05/03/2017</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	TANK BATTERY		
Comment:	Wire panels around berms and old tank battery location		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Wire panels around wellhead		
Corrective Action:			Date:
Equipment:			
Type: Ancillary equipment	# 0		corrective date
Comment:			
Corrective Action:			Date:
Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:
Flaring:			

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 271187 Type: WELL API Number: 011-06174 Status: SI Insp. Status: SI

Producing Well

Comment: [Well is TA at time of inspection. Passing MIT performed on 6/11/14](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Other	Pass			

Comment: [Location and access are grassed over](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT