

Stormwater Inspection

April 3, 2017

Operator: BONANZA CREEK ENERGY OPERATING
COMPANY LLC - #8960

API: 05-123-41116

Weld County, CO

NENE Section 21 T7N R62W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: State Crow Valley #41-21-
20XRLNB

API: 05-123-41116



Photo 1. Photo taken from the northern sediment trap along the northwest location, facing East. Minor repairs were made to the sediment trap which may be insufficient to prevent sediment laden stormwater runoff from leaving location.



Photo 2. Photo taken from the northern sediment trap along the northwest location, facing North. Minor repairs were made to the sediment trap which may be insufficient to prevent sediment laden stormwater runoff from leaving location.

Inspection Photos

Location Name: State Crow Valley #41-21-
20XRLNB

API: 05-123-41116



Photo 3. Photo taken of the northwestern location, facing South. Berm BMP has been repaired and built up higher.



Photo 4. Photo taken from the southern sediment trap along the western location, facing East. Minor repairs were made to the sediment trap which may be insufficient to prevent sediment laden stormwater runoff from leaving location.

Inspection Photos
Location Name: State Crow Valley #41-21-
20XRLNB
API: 05-123-41116



Photo 5. Photo taken of the western location, facing Southeast. Berm BMP has been repaired and built up higher.



Photo 6. Photo taken of the southwestern location, facing South. Berm BMP has been repaired and built up higher.