

Reclamation Inspection

April 3, 2017

Operator: BONANZA CREEK ENERGY OPERATING
COMPANY LLC - #8960

API: 05-123-40540

Weld County, CO

SWSE Section 31 T7N R61W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Bobcat #O-K-31HNB
API: 05-123-40540



COGCC GISOnline database aerial imagery taken in 2015. Based off aerial imagery, it appears equipment may have been on location but currently no equipment was found on location. Based off the COGCC database, this location has never been drilled.

Inspection Photos
Location Name: Bobcat #O-K-31HNB
API: 05-123-40540



Photo 1. Photo taken from the proposed well location, facing West. Location has been built but has not been drilled. Weedy, annual vegetation was apparent throughout the location with large bare spaces with no vegetation.



Photo 2. Photo taken from the proposed well location, facing North. Location has been built but has not been drilled. Weedy, annual vegetation was apparent throughout the location with large bare spaces with no vegetation.

Inspection Photos
Location Name: Bobcat #O-K-31HNB
API: 05-123-40540




Photo 3. Photo taken from the proposed well location, facing East. Location has been built but has not been drilled. Weedy, annual vegetation was apparent throughout the location with large bare spaces with no vegetation.



Photo 4. Photo taken from the proposed well location, facing South. Location has been built but has not been drilled. Weedy, annual vegetation was apparent throughout the location with large bare spaces with no vegetation.

Inspection Photos
Location Name: Bobcat #O-K-31HNB
API: 05-123-40540



Photo 5. Photo taken from the northern location, facing West. Debris has been left on location from where potential equipment was on location.



Photo 6. Photo taken from the northern location, facing Northwest. A ditch and berm BMP has been installed around the location perimeter. Minor rill erosion was observed along the fill slopes.

Inspection Photos
Location Name: Bobcat #O-K-31HNB
API: 05-123-40540



Photo 7. Photo taken from the eastern location, facing Southeast. A ditch and berm BMP has been installed around the location perimeter. Minor rill erosion was observed along the fill slopes.



Photo 8. Photo taken from the southern location, facing Southwest. A ditch and berm BMP has been installed around the location perimeter. Minor rill erosion was observed along the fill slopes.