



**Photo 1: View of the project area from the southeastern corner facing center.**



**Photo 2: View of the southern portion of the project area from the southeastern corner facing westward.**





**Photo 3: View of the eastern portion of the project area from the southeastern edge facing northward.**



**Photo 4: View of area in the eastern portion of the interim reclamation area that is eroding and needs stabilization.**





**Photo 5: View of wattles in the eastern portion of the project area that are not functioning.**



**Photo 6: View of stormwater controls and drainage to a silt trap at the edge of the project area.**



**Photo 7: View of stormwater management in the northwestern portion of the project area that appears to be functioning.**