



**Photo 1: View of the project area from the northeastern corner facing center.**



**Photo 2: View of the northern portion of the project area from the northeastern corner facing westward.**



**Photo 3: View of the eastern portion of the project area from the northeastern corner facing southward. Revegetation is sparse in this portion of the interim reclamation area and largely comprised of Indian ricegrass (*Achnatherum hymenoides*) and smooth brome (*Bromus inermis*).**



**Photo 4: View of the southern portion of the project area from the southeastern corner facing westward.**



**Photo 9: View of pipe barricade that looks like it's been knocked over.**