



Photo 1: View of the project area from the southeastern corner facing center.



Photo 2: View of the western portion of the project area from the northwestern corner facing southward. Revegetation is sparse and consistent with surrounding degraded field.



Photo 3: View of the eastern portion of the project area from the northeastern edge facing southward. Musk thistles (*Carduus nutans*) are present in the foreground.



Photo 4: View of the northern portion of the project area from the northeastern corner facing westward.



Photo 5: Another view of musk thistles within the interim reclamation area.



Photo 6: View of erosional channels in the southeastern corner of the project area.



Photo 7: View of erosional channel forming within the eastern portion of the project area.



Photo 8: View of stormwater controls in the northwestern portion of the project area appear to be functioning.