



**Photo 1:** View of the project area from the southeastern corner facing center.



**Photo 2:** View of the eastern portion of the project area from the southeastern corner facing northward. Revegetation is progressing and largely comprised of smooth brome (*Bromus inermis*).



**Photo 3: View of the southern portion of the project area from the southeastern edge facing westward.**



**Photo 4: View of the northern portion of the project area from the northeastern corner facing westward. Russian olive (*Eleagnus angustifolia*) trees appear to have been planted on the western edge of the working area.**



**Photo 5: View of headcut forming along the southern diversion in the project area. This should be carefully monitored and repaired if erosion worsens.**



**Photo 6: View of cobble check dam along the access road that is full of sediment and eroding where stormwater flows around the dam.**