

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

03/30/2017

Submitted Date:

03/31/2017

Document Number:

674603279**FIELD INSPECTION FORM**
 Loc ID 310380 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1625 BROADWAY STE 2200City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
,		NBL_DJBU_Inspections@NB LENERGY.COM	
Hazard, Ellice		ellice.hazard@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292421	WELL	PR	01/01/2017	OW	123-26326	FOSS - USX AA 5-5	EG

General Comment:

COGCC Integrity Inspection performed on March 30th, 2017 in response to initial form 19 spill report Doc #401241209 received on 03/23/2017 that outlines: During operations at the Foss USX AA 5-5 the tank load out valve developed a leak on the oil tank. The tanks were removed and excavation was initiated. The details of observations made during this field inspection are available in the tanks/ berms section of this report. Photo's have been uploaded and can be accessed via link(s) at the end of this report.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,

Comment: The 300 BBL crude oil tank has been moved out of berm area. The tank is out of service at this time. The load out ball valve has been replaced. Spill response/ remediation activities are in progress.

Corrective Action: Date: **Paint**Condition: Other (Content): Other (Capacity): Other (Type): **Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment: Corrective Action: Date: **Venting:**Yes/No: Comment: Corrective Action: Date: **Flaring:**

Type	
Comment:	<input type="text"/>
Corrective Action:	<input type="text"/>
Date:	<input type="text"/>

Inspected FacilitiesFacility ID: 292421 Type: WELL API Number: 123-26326 Status: PR Insp. Status: EG**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401248712	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114026
674603280	Signage at battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114022
674603281	New load out valve on production tank	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114023