

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/30/2017

Submitted Date:

03/31/2017

Document Number:

674703789

FIELD INSPECTION FORM

Loc ID 335709 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 53650
Name of Operator: MARATHON OIL COMPANY
Address: 1501 STAMPEDE AVENUE
City: CODY State: WY Zip: 82414

Findings:

- 9 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Jerry Beardmore	307-527-2223	jebeardmore@marathonoil.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291709	WELL	PR	10/26/2008	GW	045-14517	696-18C 27	PR
291717	WELL	PR	10/26/2008	GW	045-14511	696-18C 25	PR
291718	WELL	WO	12/17/2007	GW	045-14510	696-18C 23	WO
291719	WELL	PR	10/14/2008	GW	045-14509	696-18C 18	PR
291720	WELL	PR	04/01/2014	GW	045-14508	696-18C 16	PR
291721	WELL	PR	09/30/2008	GW	045-14507	696-18C 14	PR
291722	WELL	PR	11/11/2008	GW	045-14506	696-18C 12	PR
291785	WELL	PR	09/30/2008	GW	045-14518	696-18C 21	PR

General Comment:

Location

Lease Road:			
	Type Access		
	comment:		
	Corrective ActionL		Date:
	Type Main		
	comment:		
	Corrective ActionL		Date:

Overall Good:

Signs/Marker:			
	Type TANK LABELS/PLACARDS		
	Comment:		
	Corrective Action:		Date:
	Type WELLHEAD		
	Comment:		
	Corrective Action:		Date:
	Type BATTERY		
	Comment:		
	Corrective Action:		Date:

Emergency Contact Number:			
	Comment: 866-662-2378		
	Corrective Action:		Date: _____

Good Housekeeping:			
	Type TRASH		
	Comment:		
	Corrective Action:		Date:
	Type WEEDS		
	Comment:		
	Corrective Action:		Date:
	Type STORAGE OF SUPL		
	Comment:		
	Corrective Action:		Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 7		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	291709	Type:	WELL	API Number:	045-14517	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:				Date:					
Facility ID:	291717	Type:	WELL	API Number:	045-14511	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:				Date:					
Facility ID:	291718	Type:	WELL	API Number:	045-14510	Status:	WO	Insp. Status:	WO
Idle Well									
Purpose:	<input type="checkbox"/> Shut In	<input checked="" type="checkbox"/> Temporarily Abandoned	Reminder:						
Comment:	9/21/2012 Mechanical Integrity Test document 1772078 5 year test needed by 9/21/2017								
Corrective Action:				Date:					
Facility ID:	291719	Type:	WELL	API Number:	045-14509	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:				Date:					
Facility ID:	291720	Type:	WELL	API Number:	045-14508	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:				Date:					
Facility ID:	291721	Type:	WELL	API Number:	045-14507	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:				Date:					
Facility ID:	291722	Type:	WELL	API Number:	045-14506	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:				Date:					
Facility ID:	291785	Type:	WELL	API Number:	045-14518	Status:	PR	Insp. Status:	PR

Producing Well

Comment: Producing well on plunger lift

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
Gravel	Pass					
Compaction	Pass					
		Culverts	Pass			
Ditches	Pass					
Berms	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401248732	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4114088