

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/31/2017

Submitted Date:

03/31/2017

Document Number:

679700406

**FIELD INSPECTION FORM**

Loc ID 407304 Inspector Name: ALLISON, RICK On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 50560  
Name of Operator: LECLAIR-WESTWOOD INC  
Address: 518 17TH ST STE 1000  
City: DENVER State: CO Zip: 80202

**Findings:**

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Burn, Diana		diana.burn@state.co.us	
Axelson, John		john.axelson@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242670	WELL	PA	11/19/1981	DA	123-10461	SEVERIN & CO. 1	EI
449709	SPILL OR RELEASE	AC			-	Severin & CO #1 wellhead #1	EI

**General Comment:**

[COGCC Site Inspection of historical impacts discovered by Bayswater Exploration and Production during their re-entry and plugging of the Severin & Co. #1 well.](#)

**Inspected Facilities**

Facility ID: 242670 Type: WELL API Number: 123-10461 Status: PA Insp. Status: EI

Facility ID: 449709 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

## Environmental

**Waste Management:**

Type	Management	Condition	GPS (Lat) (Long)
Oily Soil	Piles	Adequate	
Comment		Operator has stockpiled ~15 yds oily soil on liner, to be disposed at commercial facility	
Corrective Action			Date:

**Spill/Remediation:**

Comment: COGCC onsite to inspect and sample historical impacts discovered during re-entry and P&A of well. Operator had excavated approximately 15'x15'x5' to accomodate cut and cap of the well casing. Impacts are present in the sidewalls and floor of excavation. Excavated soil and sidewalls have hydrocarbon odor. Soil sample collected and delivered to laboratory for analysis for TPH-DRO, TPH-GRO and BTEX. Sample collected from northwest corner of excvation at approximately 4' below ground surface, Lat/Lon = 40.54330 / -104.79086

Corrective Action:

Date: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401248650	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4113957">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4113957</a>
679700407	Soil Sample Chain of Custody	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4113942">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4113942</a>
679700408	View of stockpiled soil 1	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4113943">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4113943</a>
679700409	View of stockpiled soil 2	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4113944">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4113944</a>
679700410	From south side of excavatino looking north	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4113945">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4113945</a>
679700411	From east side of excavation looking west	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4113946">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4113946</a>