

Stormwater Inspection

April 6, 2017

Operator: BURLINGTON RESOURCES OIL & GAS LP
#26580

Location ID: 442484

Arapahoe County, CO

SESE Section 18 T4S R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: Montezuma 4-64 18-13 #4H

Location ID: 442484



Photo 1. Photo taken from the entrance of location, facing East. Access road into entrance has been constructed.



Photo 2. Photo taken from the southeast location, facing Southeast. A stabilized outlet has been installed with a filter wattle.

Inspection Photos

Location Name: Montezuma 4-64 18-13 #4H

Location ID: 442484



Photo 3. Photo taken from the southwest production area, facing East. Diversion ditch installed in conjunction with a sediment trap.



Photo 4. Photo taken from the western production area, facing East. Diversion ditch installed in conjunction with a sediment trap. Operator said that filtrex will be installed along the western disturbance area.

Inspection Photos

Location Name: Montezuma 4-64 18-13 #4H

Location ID: 442484



Photo 5. Photo taken from the northwest location, facing Northwest. Sediment trap has been installed in conjunction with diversion ditches and filtrex installed along the outer perimeter of the disturbance area.



Photo 6. Photo taken from the sediment trap, facing South. Sediment trap has been installed with a stabilized outfall and principle outlet.

Inspection Photos

Location Name: Montezuma 4-64 18-13 #4H

Location ID: 442484



Photo 7. Photo taken from the eastern production area, facing North. Diversion ditch has been installed in conjunction with a sediment trap.



Photo 8. Photo taken from the eastern production area, facing South. Diversion ditch has been installed in conjunction with a sediment trap.

Inspection Photos

Location Name: Montezuma 4-64 18-13 #4H

Location ID: 442484



Photo 9. Photo taken from the topsoil stockpile along the eastern location, facing North. Filtrex has been installed along the toe of the topsoil stockpile with a diversion ditch to the outside to control run-on.



Photo 10. Photo taken from the topsoil stockpile along the eastern location, facing South. Filtrex has been installed along the toe of the topsoil stockpile with a diversion ditch to the outside to control run-on.