

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/06/2017

Submitted Date:

04/10/2017

Document Number:

682401969**FIELD INSPECTION FORM**Loc ID 442484 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 26580Name of Operator: BURLINGTON RESOURCES OIL & GAS LPAddress: PO BOX 4289City: FARMINGTON State: NM Zip: 87499**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☒
- NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Prasanna, Sonu		Sonu.Prasanna@conocophillips.com	All Inspections
Strickler, Robert		robert.d.strickler@conocophillips.com	
Farrell, Larissa		Larissa.L.Farrell@conocophillips.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
442485	WELL	XX	07/15/2015	LO	005-07242	Montezuma 4-64 18-13 4H	RI

General Comment:[This is a follow up stormwater inspection to FIR Document #682401919.](#)

Inspected Facilities									
Facility ID:	442485	Type:	WELL	API Number:	005-07242	Status:	XX	Insp. Status:	RI

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Gravel	Pass			
Sediment Traps	Pass					
Waddles	Pass					Filtrex
Culverts	Pass					
Rip Rap	Pass					

Comment: A diversion ditch has been installed around the production area in conjunction with a sediment trap. The sediment trap has been installed along the northwest location perimeter with a stabilized outfall and principle outlet. Filtrex has been installed around toe slope of the topsoil stockpile and around the disturbance area of the sediment trap. The Operator stated that filtrex will be installed along the western disturbance area. In addition, a diversion ditch has been installed along the eastern and northern area to control run-on onto location.

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
BMPs should remain in place and in proper functioning condition until the location reaches final reclamation.	binschusc	04/10/2017
Refer to attached inspection photos in Document #682401970.	binschusc	04/10/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682401970	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4120010