



Photo 1: View of the project area from the northeastern corner facing center.



Photo 2: View of the northern portion of the project area from the northeastern corner facing westward. Most of the revegetation is not in identifiable form but is largely comprised of grasses such as intermediate wheatgrass (*Thinopyron intermedium*).



Photo 3: View of the eastern portion of the project area from the northeastern corner facing southward.



Photo 4: View cobble run-down along the access that appears to be functioning.



Photo 5: View of stormwater controls newly installed within the southern portion of the project area. Appear to be functioning at this time. Area is recently seeded.



Photo 6: View of the southern portion of the project area from the southwestern corner facing eastward.