

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/04/2017

Submitted Date:

04/04/2017

Document Number:

675204090

FIELD INSPECTION FORM

Loc ID 334468 Inspector Name: CONKLIN, CURTIS On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100185
Name of Operator: ENCANA OIL & GAS (USA) INC
Address: 370 17TH ST STE 1700
City: DENVER State: CO Zip: 80202-

Findings:

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Hartman, Robert	(970) 244-3041	bhartman@blm.gov	Petroleum Engineer
Encana,		cogcc.inspections@encana.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297471	WELL	PR	11/05/2012	GW	045-16849	FEDERAL 1-14 (ON-1)	PR
297472	WELL	PR	11/28/2012	GW	045-16850	FEDERAL 1-13(ON-1)	PR
297473	WELL	PR	01/01/2014	GW	045-16851	FEDERAL 1-11(ON1)	PR
297474	WELL	PR	02/20/2013	GW	045-16852	FEDERAL 1-15(ON1)	PR
423709	WELL	PR	11/03/2011	GW	045-20792	FEDERAL 36-1H (ON1)	PR

General Comment:

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLS	STEEL AST		,
Comment:	<input type="text"/>				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	<input type="text"/>			
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:	<input type="text"/>		
Corrective Action:			Date:

Flaring:

Type	<input type="text"/>
------	----------------------

Comment:		
Corrective Action:	Date:	

Inspected Facilities

Facility ID: 297471 Type: WELL API Number: 045-16849 Status: PR Insp. Status: PR

Facility ID: 297472 Type: WELL API Number: 045-16850 Status: PR Insp. Status: PR

Facility ID: 297473 Type: WELL API Number: 045-16851 Status: PR Insp. Status: PR

Facility ID: 297474 Type: WELL API Number: 045-16852 Status: PR Insp. Status: PR

Facility ID: 423709 Type: WELL API Number: 045-20792 Status: PR Insp. Status: PR

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Culverts	Pass			
Berms	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401251317	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4116108
675204091	ON 1 Pad	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4116035