



**Environmental**

**Spills/Releases:**

Type of Spill: PRODUCED WATER Estimated Spill Volume: \_\_\_\_\_

Comment: Inspection to assess closure/remediation of pit under REM 10109 by Geotechnical Engineering Group, Inc. Signage has been changed to indicate new Operator as Lasso. 300 bbl crude tank is in dirt berm. Pit is small unlined and out of service. Spill report indicated 685ppm TPH in pit soil. No visible staining or odor in pit. Water in pit (run on snowmelt) has no sheen. Steve of Target Trucking pumps entire volume of pit (20bbl) for offsite disposal.

Corrective Action: Complete excavation and offsite disposal of petroleum contaminated soils. Remediate to Table 910-1 standards and provide documentation. Documentation must include a figure showing spill area with sample locations plus laboratory results. Backfill and close pit in accordance with COGCC rules.

Date: 05/31/2017

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401251674	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4116667">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4116667</a>
674300873	Pit following pumpout	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4116665">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4116665</a>