

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/31/2017

Submitted Date:

04/05/2017

Document Number:

674901575**FIELD INSPECTION FORM**
 Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
 Hughes, Jim \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 77330Name of Operator: SG INTERESTS I LTDAddress: 100 WAUGH DR SUITE 400City: HOUSTON State: TX Zip: 77007**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Inspections, All		inspections@sginterests.com	<a href="#">All Inspections</a>
Ikenouye, Teri		teri.ikenouye@state.co.us	

**General Comment:**

On March 31, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the SG Interests Pit Facility ID #115773. The purpose of this site visit was to document the physical status of this pit facility. Pit facility ID #115773 shall be administratively closed in the COGIS database after desktop review and this field inspection. No surface indication of pits.

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PITType:  Lined:  Pit ID: 115773 Lat: 37.127548 Long: -107.878348Reference Point:  Other:  Length:  Width: **Lining:**Liner Type: Liner Condition: Comment: Location inspection conducted to determine physical existence of pit facility ID #115773.Corrective Action Date: c**Fencing:**Fencing Type: Fencing Condition: Comment: Corrective Action Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action Date: Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard: Comment: Corrective Action Date: **COGCC Comments**

Comment	User	Date
<u>On March 31, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the SG Interests Pit Facility ID #115773. The purpose of this site visit was to document the physical status of this pit facility. Pit facility ID #115773 shall be administratively closed in the COGIS database after desktop review and this field inspection. No surface indication of pits.</u>	hughesj	04/05/2017

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401252036	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4116967">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4116967</a>
674901576	Samson open topped PW vessel.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4116964">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4116964</a>
674901577	Bondad 33-10 #9 location photo.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4116965">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4116965</a>

