

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/03/2017

Submitted Date:

04/05/2017

Document Number:

682401965**FIELD INSPECTION FORM**

Loc ID 159489 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 8960Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANYAddress: 410 17TH STREET SUITE #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		EHSRC@bonanzacrk.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
440780	WELL	PR	08/01/2015	OW	123-41116	State Crow Valley 41-21-20XRLNB	RI

**General Comment:**

This is a follow up stormwater inspection to FIR Document #682401747 and in response to FIRR Document #401213467 stating that corrective actions have been performed.

Inspected Facilities				
Facility ID: 440780	Type: WELL	API Number: 123-41116	Status: PR	Insp. Status: RI
Producing Well				
Comment:	PR, stormwater inspection			
Corrective Action:				Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Sediment Traps	Pass					see comments
Berms	Pass					

Comment: Repairs were made to the berm BMP along portions of the northern and southern location, and along the western location. Berm BMP has been repaired and built up higher. Appears minor repairs were made to the sediment traps. Appears the holding capacity for both sediment traps may be insufficient. Wattles are being used as outlet protection which may not be appropriate for long-term outlet protection as wattles are a temporary BMP. The performed work on the sediment traps may be insufficient to prevent sediment laden stormwater runoff from leaving location. As it was noted in the previous inspection, sediment discharge was evident from the outlet areas on both sediment traps.

Corrective Action:

Date: \_\_\_\_\_

Pits: ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<a href="#">Refer to attached inspection photos in Document #682401966.</a>	binschusc	04/05/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401251936	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4116904">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4116904</a>
682401966	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4116893">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4116893</a>