



Photo 1: View of the project area from the southwestern corner facing center.



Photo 2: View of the southern portion of the project area from the southwestern corner facing eastward. Revegetation within the project area is progressing with grasses such as blue grama (*Bouteloua gracilis*), and western wheatgrass (*Pascopyrum smithii*), and others not in identifiable form.



Photo 3: View of the western portion of the project area from the southwestern corner facing northward.



Photo 4: View of the eastern portion of the interim reclamation area from the southeastern corner facing northward.



Photo 5: View of flowline alignment, revegetation appears to be progressing.



Photo 6: View of stormwater controls along the access road, appear to be functioning.