

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/23/2017

Submitted Date:

04/06/2017

Document Number:

680601421**FIELD INSPECTION FORM**

Loc ID 326275 Inspector Name: ROY, CATHERINE On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 16695Name of Operator: CHEVRON MIDCONTINENT LPAddress: 6301 DEAUVILLE BLVDCity: MIDLAND State: TX Zip: 79706**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216152	WELL	PR	02/04/2000	GW	067-07758	LAPALOMA 1-2	RI

General Comment:

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: Project area is surrounded by pinion juniper woodland. Revegetation is progressing within the interim reclamation areas. See attached photos.**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING _____

Comment Corrective Action

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____Comment Corrective Action

Date _____

1002c. PROTECTION OF SOILS _____

Comment Corrective Action

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment Corrective Action

Date _____

1003a. Waste and Debris removed? PassComment Corrective Action

Date _____

Unused or unneeded equipment onsite? PassComment Corrective Action

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment Corrective Action

Date _____

Guy line anchors marked? _____

Comment Corrective Action

Date _____

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
<p>Comment: Headcut erosion is forming in the southern diversion and needs to be monitored and repaired if erosion worsens. Erosion is occurring along the access road where BMPs are full of sediment and need maintenance/repair. Vegetation is helping to stabilize erosion within the project area.</p> <p>Corrective Action: Monitor and repair diversion if erosion worsens. Maintain and repair stormwater BMPs within the project area.</p>						Date: 05/12/2017
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401252927	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4117868
680601422	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4117863