

Stormwater Inspection

April 3, 2017

Operator: NOBLE ENERGY INC- #100322

Location ID: 445257

Weld County, CO

NWNE Section 22 T9N R59W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: LC22-02 /PAD
Location ID: 445257




Photo 1. Photo taken from the northeast location, facing South. Surface roughening has been installed along the perimeter of the location, in conjunction with a tackifier along portions of the fill slope. A 12"-16" berm has been installed along the production area.



Photo 2. Photo taken from the northeast location, facing Southeast. Photo illustrates current stormwater BMPs.

Inspection Photos
Location Name: LC22-02 /PAD
Location ID: 445257




Photo 3. Photo taken from the southeast location, facing South. Surface roughening has been installed along the location perimeter. A large undisturbed, vegetated area exists between the production area and the temporary BMP- surface roughening. A portion of the fill slope does not appear to be stabilized.



Photo 4. Photo taken from the southeast location, facing Southwest. Topsoil stockpile has been stored along the southern location and a tackifier applied.

Inspection Photos
Location Name: LC22-02 /PAD
Location ID: 445257



Photo 5. Photo taken from the western location, facing South. Surface roughening has been installed along the perimeter of the location, in conjunction with a tackifier along portions of the fill slope. A 12"-16" berm has been installed along the production area.