



Photo 1: View of the project area from the southwestern corner facing center.



Photo 2: View of the southern portion of the project area from the southwestern corner facing eastward. Revegetation within the project area is progressing with grasses and shrubs such as smooth brome (*Bromus inermis*) and rubber rabbitbrush (*Chrysothamnus nauseosus*).



Photo 3: View of the western portion of the project area from the southwestern corner facing northward.



Photo 4: View of the northern portion of the interim reclamation area from the southwestern corner facing eastward.



Photo 5: View of area where concentrated stormwater flows off of the southern edge of the well pad.



Photo 6: View of sediment deposition downstream of erosion occurring in Photo 5.