

Inspection Photos
Location Name: Myers F-1
API: 05-123-10334



Photo from prior inspection for comparison



Photo 1: Weeds controlled at pump jack, stained soil at pump jack

Inspection Photos
Location Name: Myers F-1
API: 05-123-10334



Photo from prior inspection for comparison



Photo 2: Stained soil at wellhead removed.

Inspection Photos
Location Name: Myers F-1
API: 05-123-10334



Photo from prior inspection for comparison



Photo 3: Debris removed from treater house

Inspection Photos
Location Name: Myers F-1
API: 05-123-10334



Photo from prior inspection for comparison



Photo 4: Weeds controlled at treater

Inspection Photos
Location Name: Myers F-1
API: 05-123-10334



Photo from prior inspection for comparison



Photo 5: Tanks are placarded, stenciled

Inspection Photos
Location Name: Myers F-1
API: 05-123-10334



Photo from prior inspection for comparison



Photo 6: Weeds removed, operator on sign, no emergency contact number



Inspection Photos
Location Name: Myers F-1
API: 05-123-10334



Photo from prior inspection for comparison



Photo 7: Stained soil removed

Inspection Photos
Location Name: Myers F-1
API: 05-123-10334



Photo 8: Low berms at tank battery

