

Inspection Photos  
Location Name: Tow Creek 11-13  
API: 05-107-06051



**Photo 1. View at entrance to location facing southeast. 1 of 3 unlabeled propane tanks visible in foreground.**



Inspection Photos  
Location Name: Tow Creek 13-11  
API: 05-107-06051



Photo 2. Stained soil at pump jack exhaust.



Photo 3. Stained soil at wellhead.