

Construction and Stormwater Inspection

April 7, 2017

Operator: KERR MCGEE OIL & GAS ONSHORE LP
#47120

Location ID: 330770

Weld County, CO

NWNW Section 10 T2N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: BUTTERBALL /32C-34HZ
Location ID: 330770



Photo 1. Photo taken from the entrance of location, facing East. Vehicle tracking pad installed but does not appear to be a sufficient amount of material. Monitor vehicle tracking and potential sediment discharge.



Photo 2. Photo taken from the southeastern location, facing West. Ditch and berm BMP installed around the perimeter of location. Also, location is dominated by sandy soils so a tackifier is recommended to stabilize all disturbed areas to control for wind erosion.

Inspection Photos
Location Name: BUTTERBALL /32C-34HZ
Location ID: 330770



Photo 3. Photo taken from the southern location, facing Northeast. Topsoil stockpile stored along the southern perimeter of the location.



Photo 4. Photo taken from the southwest location, facing North. Ditch and berm BMP installed around the perimeter of location. Also, location is dominated by sandy soils so a tackifier is recommended to stabilize all disturbed areas to control for wind erosion.

Inspection Photos
Location Name: BUTTERBALL /32C-34HZ
Location ID: 330770



Photo 5. Photo taken from the western location, facing North. Ditch and berm BMP installed around the perimeter of location. Also, location is dominated by sandy soils so a tackifier is recommended to stabilize all disturbed areas to control for wind erosion.



Photo 6. Photo taken from the northwest location, facing North. Sediment trap installed and IN-PROCESS of being completed (i.e., outlet still needs to be stabilized). Also, location is dominated by sandy soils so a tackifier is recommended to stabilize all disturbed areas to control for wind erosion.

Inspection Photos
Location Name: BUTTERBALL /32C-34HZ
Location ID: 330770



Photo 7. Photo taken sediment trap, facing Southeast. Sediment trap installed and IN-PROCESS of being completed (i.e., outlet still needs to be stabilized).



Photo 8. Photo taken from the northwest location, facing East. Ditch and berm BMP installed around the perimeter of location. Also, location is dominated by sandy soils so a tackifier is recommended to stabilize all disturbed areas to control for wind erosion.

Inspection Photos
Location Name: BUTTERBALL /32C-34HZ
Location ID: 330770



Photo 9. Photo taken from the northeast location, facing South. Ditch and berm BMP installed around the perimeter of location. Also, location is dominated by sandy soils so a tackifier is recommended to stabilize all disturbed areas to control for wind erosion.



Photo 10. Photo taken from the eastern location, facing South. Existing irrigation ditch travels south, east of location.