

Inspection Photos
Location Name: Titanium 26-10-7HI & 2
API: 05-057-06094



Photo 1. View of location at entrance facing west.



Photo 2. Torn sign at entrance.

Inspection Photos
Location Name: Titanium 26-10-7HI & 2
API: 05-057-06094



Photo 3. Unlabeled containers at wellhead. One without secondary containment.



Photo 4. No capacity on produced water tank.